

Collision Between Pickup Truck with Trailer and Group of Motorcycles Randolph, New Hampshire

Randolph, New Hampshire June 21, 2019

1

Virtual Board Meeting Staff Participants

Rob Molloy, PhD Director, Office of Highway Safety (OHS)

• Ensar Becic, PhD Project Manager (OHS)

Kenneth Bragg Investigator-in-Charge (OHS)

Dennis Collins Human Performance Factors (OHS)

Michael Fox Motor Carrier Factors (OHS)

Ronald Kaminski Survival Factors (OHS)Brian Bragonier Vehicle Factors (OHS)

Bob Squire Technical Reconstruction (OHS)

Dan Walsh Highway Factors (OHS)

Mary Pat McKay, MD Medical Officer, Office of Research & Engineering

2

® NTSB


Virtual Board Meeting Staff Participants Dolline Hatchett Director, Office of Safety Recommendations and Communications (SRC) Deputy Director, General Counsel Casey Blaine Director, Research and Engineering James Ritter Safety Recommendations (SRC) Julie Perrot Steve Blackistone Government Affairs (SRC) Visuals (OHS) Mark Bagnard Kristin Poland, PhD Acting Report Development Chief* (OHS) Monica Mitchell Report Editor (OHS) *Dr. Poland is Deputy Director for OHS and serving as the Chief of the Report Development Division **(R)** NTSB

National
Transportation
Safety Board

Randolph, New Hampshire
June 21, 2019

Kenneth Bragg
Investigator-in-Charge
















ç

















Injuries • Motorcycle Riders - 5 fatal - 1 serious - 4 minor • Motorcycle Passengers - 2 fatal - 2 minor • Pickup Truck Driver - none

17



Report Development Staff • Ensar Becic, PhD, Project Manager • Monica Mitchell, Report Editor • Julie Perrot, Safety Recommendations • Robert Squire, Technical Reconstruction • Dan Walsh, PE, Highway Factors • Mary Pat McKay, MD, Medical Factors

19

Parties to the Investigation New Hampshire State Police Federal Motor Carrier Safety Administration USDOT, Office of the Inspector General NTSB

Safety Issues

- Deficiencies in out-of-state driver's license notification processing
- Insufficient federal oversight of motor carriers
- Shortcomings in motorcycle rider safety

21

₩ NTSB


21

Staff Presentations

- Operator Actions
- Interstate Communication about License Suspension
- Federal Oversight of Motor Carriers
- Motorcycle Helmet Safety
- Motorcycle Rider Safety

22

₩ NTSB



Overview


- Excluded human performance factors of the driver
- Pickup driver's
 - Actions and statements
 - Substance abuse
 - Fatigue
- Interstate communication about license suspension

2

W NTSB

Excluded Factors Pickup truck driver's experience Cell phone distraction Weather – fair, good visibility, dry roadway

25



Pickup Truck Driver's Statements

- Driver arrested three days after crash; told police about history of heroin/cocaine use
- Used heroin and cocaine the morning of crash
- Was feeling effects of drugs and used caffeine to take edge off before the crash

27

® NTSB


27

Pickup Truck Driver's Substance Abuse

- Toxicology showed multiple drugs & metabolites
- Levels indicate use within 12 hours
- Centerline crossing most likely due to impairment from the multiple drugs
- Determining specific effects of individual drugs not possible

28

W NTSB



Revocation of Connecticut Driving Privileges Driver stopped May 11, 2019 (45 days) Refused urine drug test Refusal triggered Connecticut suspension Connecticut sent electronic notice to Massachusetts on May 29, effective June 10 Paper notice also sent to Massachusetts

Out-of-State Sanctions in Massachusetts

- Suspended/revoked/canceled in another state = revoked in Massachusetts
- License should have been revoked June 10, 2019 until at least July 25, 2019
- Connecticut notices were not processed, pickup truck driver's license NOT revoked

31

₩ NTSB


31

Massachusetts RMV Audit and Review

- Electronic notice
 - Received by Massachusetts software (ATLAS) May 29, 2019
 - ATLAS could not process future dates
 - Diverted into a queue; queue never monitored or processed
 - 365 e-notices, 3 not resolved by other means, only this driver was automatic revocation

32

(NTSB



Massachusetts RMV Systemic Deficiencies

- Failure to process notifications for years means systems were ineffective
- Effective systems = revoked licenses
- Systemic deficiencies and inaction resulted in failure to suspend thousands of licenses, many noncommercial

34

₩NTSB

Massachusetts Actions After Audit/Review

- Modified ATLAS to process future dates
- Created Out-of-State (OOS) Unit to handle all out-of-state notifications
- Created workflow for notifications
- Assigned specific personnel to notifications
- Required daily status updates to management

35

W NTSB

35

Massachusetts Actions After Audit/Review

- Changes made represent progress
- If maintained, should reduce likelihood of drivers incorrectly retaining MA licenses
- Massachusetts DOT should regularly evaluate RMV's processing of all out-of-state notifications

36

W NTSB

Notification Issues Are Widespread

- Rhode Island 22,500+ not reported to MA
- New Hampshire 3,852 (7 CDL) suspended
- · Reported issues in at least six jurisdictions
- Improved communication will improve safety
- Jurisdictions should perform review of incoming/outgoing notice processes

37

₩NTSB

37

Summary

- Pickup driver
 - Excluded experience, cell phone use
 - Fatigue effect undetermined
 - History of drug use, drugs in system
 - Crossing centerline most likely the result of impairment from use of multiple drugs

38

W NTSB


Summary

- Massachusetts Registry of Motor Vehicles
 - Should have revoked the pickup driver's license
 - Was not properly processing notifications
 - Changes represent progress, monitoring needed
- General
 - Issues not limited to Massachusetts; other jurisdictions should examine their processes

39


₩ NTSB

39



Overview Westfield Transport operations Precrash Postcrash compliance review (CR) FMCSA oversight of motor carriers Oversight of Westfield Transport Use of imminent hazard orders FMCSA oversight of electronic logging device (ELD) providers

41



Postcrash Investigation of Westfield Transport

- FMCSA compliance review
 - Carrier was noncompliant with regulations
 - 25 violations: 4 acute, 3 critical, 18 additional
 - Unsatisfactory safety rating
- Additional deficiencies
 - Carrier did not have drug testing program, safety plan, written policies, driver training
 - Owner lied and tampered with ELDs

43

₩ NTSB

43

Carrier's Inadequate Oversight of Drivers

- Accident driver
 - Incomplete driver qualification (DQ) files: missing background check, accident history
- Other drivers
 - Incomplete DQ files
 - Using a driver with revoked CDL
 - Tampered with ELDs / 28 of 150 examined logs falsified

44

MISB

FMCSA Oversight of Westfield Transport

- Postcrash investigation revealed a carrier without regard for safety
 - How did the carrier reach that point?
- FMCSA oversight during different segments of carrier's life
 - During the new entrant period (increased scrutiny)
 - After the new entrant period (standard oversight)

45

● NTSB

45

FMCSA Oversight of Westfield Transport									
New entrant:	Period	Vehicles	Roadside Inspections	OOS Violations	BASICs in Alert				
July 2016 – January 2018	18 months (new entrant)	1-2	7	2	0-1				
Exited program: January 2018	13 months (post-new entrant)	2-11	31	15	1-2				
February 2019: Moderate-risk	5 months (post-new entrant)	8	17	8	3				
46				(©) N⁻	тѕв				
46				N N	ISB				

Oversight of Recent New Entrant Graduates

- One-third of motor carriers do not complete the new entrant program
- Same level of oversight for recent graduates and longstanding carriers
 - Dramatic increase in inspections and violations
- Stronger oversight of recent graduates of new entrant program is necessary

47

₩NTSB

47

Reincarnated Motor Carriers

- Westfield Transport had 21 affiliations with other carriers
- Avoid and elude FMCSA = reincarnated carrier
- Other Westfield Transport affiliations
 - DAKS Express place of business associated with accident driver but lived in Florida and maintained fleet in Florida
 - East2West Transport driver now owner, 1 shared driver, and using 6 of Westfield's vehicles

48

W NTSB

Westfield Transport Imminent Hazard Order

- FMCSA investigator initiated imminent hazard paperwork, but the FMCSA did not issue the IH order
- IH orders remove unsafe carriers and prevent reincarnation
- FMCSA stated IH standard was not met and none of the discovered violations impacted the June 21 crash
- Carrier's actions did directly impact the crash

49



49

Imminent Hazard Orders

- Previous NTSB recommendation about IH orders
 - Naperville, IL, H-16-1; no progress on implementation
- In recent years, the FMCSA has inconsistently and rarely used IH orders

	Year												
	2000 - 2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020
IH Order	14 ª	9	2	15	43	32	11	6	7	3	1	0	0

^a Only passenger- and hazardous-material motor carriers were issued IH orders during 2000–2008. The orders in the subsequent years were issued to all types of carriers, including freight.

50



Oversight of ELD Providers

- ELDs designed to be accurate and tamperproof
- KeepTruckin ELDs Westfield Transport able to easily tamper and falsify
- Thoreau, New Mexico, also tampered with the KeepTruckin device
- Remove KeepTruckin from approved list
- Revise the process for ELDs to become approved

5


51

Summary

- Westfield Transport operated without regard for safety
- FMCSA oversight for Westfield was inadequate
- Proposed recommendations would strengthen FMCSA's oversight of recent new entrant graduates and ELD providers

52

MISB




Overview

- Injuries to riders and passengers
- Motorcyclists' helmet use
- FMVSS 218 motorcycle helmet standards
- Benefits of USDOT-compliant helmets
- Previous motorcycle helmet recommendations

5

® NTSB



Formation's Helmet Use Of the 18 meters validte

- Of the 18 motorcyclists
 - 12 were wearing USDOT-compliant helmets
 - 1 was wearing a non-compliant helmet
 - Lead rider was most likely not wearing any helmet
 - Helmet use for 4 is unknown
- New Hampshire does not require helmet use

56

® NTSB

Formation's Helmet Use

- Of the 7 motorcyclists who died
 - 3 were wearing USDOT-compliant helmets
 - Helmet use for 3 is unknown
 - Lead rider not protected
- Six motorcycles—carrying 8 motorcyclists—were directly struck by the combination vehicle
 - Only one of those riders survived, with serious injuries

57



57

Benefits of USDOT-Compliant Helmets

- NHTSA's analysis
 - Helmets are 37% effective for riders and 41% effective for passengers
- NHTSA estimated that USDOT-compliant helmets saved 1,872 lives in 2017
 - Another 749 lives could have been saved with all motorcyclists helmeted



Helmets Use and State Laws

- Nationally, USDOT-compliant helmet use in 2019 was 71%
- 18 states and Washington D.C. have mandatory universal helmet-use laws
 - Helmet use is 89%
- 29 states have partial helmet-use laws; 3 states have no helmet-use laws
 - Helmet use drops to 56%

59



59

Motorcycle Helmet Safety

- NTSB Motorcycle Safety Forum (2006)
 - Issued 3 recommendations to require universal helmet laws in all states
 - Specification for USDOT-compliant helmets
- High fatality rate persists since the issuance of the recommendations: 4,985 died in 2018
- Due to lack of progress on these recommendations, renewed focus is needed




Summary

- USDOT-compliant helmets have been shown to provide the best protection for motorcyclists
- Reiterate Safety Recommendations H-07-38 through -40
- USDOT-compliant helmets can save lives, but only when used

61

W NTSB

61



Overview

- Motorcycle antilock braking systems (ABS)
- NHTSA's ABS regulations and performance standards
- Motorcycle rider safety
 - Impairment
 - Spacing

63

● NTSB

63

Motorcycle Antilock Braking Systems

- Motorcycles have reduced stability at low speeds or during wheel lock-up
- ABS improves stability by preventing wheel lock-up
 - 109% increase in crash risk without ABS

6

W NTSB

Motorcycle Antilock Braking Systems

- Four involved motorcycles equipped with ABS
- Two riders stated they believed ABS helped them stop in a controlled manner
- Likely aided riders in performing emergency braking during crash sequence

65

₩NTSB

65

NHTSA's ABS Performance Standards

- NHTSA does not require ABS on motorcycles
 - Federal Motor Vehicle Safety Standard (FMVSS)
 122 specifies ABS performance requirements
- NTSB has issued a safety recommendation to NHTSA to require motorcycle ABS
 - Classified "Open Unacceptable Response"

66

W NTSB

Motorcyclist Alcohol Use

- Alcohol + motorcycles = higher risk
- In 2016, a quarter of all motorcycle rider fatalities had BAC over 0.08g/dl
- Alcohol use increases response time

67

₩NTSB

67

Motorcyclist Alcohol Use

- Four of six riders tested were positive for alcohol
- Lead rider above New Hampshire per se limit of 0.08 g/dL
- · Lead rider impaired, undetermined effect
- Unlikely that other riders could have avoided the oncoming pickup truck

68

MISB

Motorcycle Spacing

- Staggered formation
 - Left and right column within the lane of travel
 - 2-second following distance between riders on the same side of <u>formation</u>
- Involved riders entered roadway just prior to crash
 - No time to develop formation and spacing

69

69

Motorcycle Safety

- National Association of State Motorcycle Safety Administrators and the Motorcycle Safety Foundation
 - Inform members about this crash
 - Safety benefits of ABS-equipped motorcycles, unimpaired riding, spacing, and USDOTcompliant helmets

70

W NTSB

Summary ABS is a proven safety system Never ride after consuming alcohol Maintain proper following distance Always wear a USDOT-compliant helmet